

This Page Is Inserted by IFW Operations  
and is not a part of the Official Record

## **BEST AVAILABLE IMAGES**

Defective images within this document are accurate representations of the original documents submitted by the applicant.

Defects in the images may include (but are not limited to):

- BLACK BORDERS
- TEXT CUT OFF AT TOP, BOTTOM OR SIDES
- FADED TEXT
- ILLEGIBLE TEXT
- SKEWED/SLANTED IMAGES
- COLORED PHOTOS
- BLACK OR VERY BLACK AND WHITE DARK PHOTOS
- GRAY SCALE DOCUMENTS

**IMAGES ARE BEST AVAILABLE COPY.**

**As rescanning documents *will not* correct images,  
please do not report the images to the  
Image Problem Mailbox.**




Figure 1:

# New Wheel Slip Valve - Prior Art




Figure 2:

Pressure Rate Request - PRR

# Old Wheel Slip Valve - Prior Art





Figure 3:

Pressure Rate Request - PRR

# New & Old Wheel Slip Valve - Smart Resolution Valve Pressure Control



Pressure Rate Request - PRR

Figure 4:




Figure 5




Figure 6